

Transducer Installation	Date	Time	Depth to Water*	Depth to Bottom	Water Thickness (ft)	Notes
SDMH-24A	12/3/2010	Recorded on transducer	10.23	Not measured		Slight flow visible toward LDW, small puddles at bottom and fairly hard bottom.
SDMH-24B	12/3/2010	Recorded on transducer	10.35	Not measured		Slight flow visible toward LDW, small puddles at bottom and soft bottom.
SDMH-37-7	12/3/2010	Recorded on transducer	9.80	Not measured		Small puddles at bottom and solids visible, soft bottom.
SDMH-37-2	12/3/2010	Recorded on transducer	10.23	Not measured		Small puddles at bottom and solids visible, soft bottom.
Public SDMH-11	12/3/2010	Recorded on transducer	9.09	Not measured		Only a couple of inches of water visible, water coming in from lateral at low rate.

Surface Water Sampling	Date	Time	Depth to Water*	Depth to Bottom*	Water Thickness (ft)	Notes
SDMH-24A	12/22/2010	8:00	6.90	10.52	3.62	No movement of water observed, hard bottom.
SDMH-24B	12/22/2010	8:30	7.66	10.58	2.92	No movement of water observed, soft bottom.
SDMH-37-7	12/22/2010	8:50	7.96	10.05	2.09	No movement of water observed, soft bottom.
SDMH-37-2	12/22/2010	9:15	8.89	10.4	1.51	Slight movement of water observed toward LDW as tide running out, hard bottom.
Public SDMH-11	12/22/2010	9:30	8.85	9.54	0.69	Slight movement of water observed toward LDW as tide running out, hard bottom; no water coming in from lateral.

*Measured from top lip of manhole cover.